PORTAUTHORITY. Part Authority® Flexifi® Garment-Washed Cap. 2009 Image: Construction of the serve of the se



back

HOW TO MEASURE

HATS

Measure the circumference around the head, above the eyebrow and at the widest part of the head. Divide number by 3.14 for hat size.

SIZE CHART

	S/M	L/XL
Hat Size	6 3/4 - 7 1/4	7 1/8 - 7 5/8
Head Size	21 1/4- 22 3/4	22 3/8- 23 7/8

COLOR INFORMATION









